



Replacement Sheet

FIG.24  
(PRIOR ART)






FIG.25  
(PRIOR ART)



Addendum to Amendment

FIG. A


1 0 ... コネクタ本体  
1 4 ... 保持部  
1 2 0 ... バイアス部  
2 1 ... 先端部  
2 2 ... 環状突起  
2 3 ... 第一環状突起  
3 0 ... 第二環状突起  
3 2 ... 止止め爪部  
4 0 ... U字状横壁  
4 1 ... 第一横壁  
4 2 ... 第二横壁  
4 3 ... 第三横壁  
4 6 ... 突出部



Addendum to Amendment

FIG. B

1 0 ...コネクタ本体  
1 4 ...保持部  
2 0 ...バイアス部  
2 1 ...先端部  
2 2 ...第1環状突起  
2 3 ...第2環状突起  
3 0 ...リテラル  
3 2 ...a...抜き爪部  
4 0 ...b...クランプ状止止め部  
4 1 ...c...U字状横壁間部  
4 2 ...d...第1横壁  
4 3 ...e...第2横壁  
4 4 ...f...第1側面  
4 4 ...g...第2側面  
4 4 ...h...内凹面  
4 4 ...i...内凹面  
4 5 ...j...第1側面  
4 5 ...k...第2側面  
4 5 ...l...内凹面  
4 6 ...m...第1側面  
4 7 ...n...突起部  
4 7 ...o...貫通孔



Application No. 10/768,500  
Amendment Dated April 28, 2005  
Reply to Office Action of November 29, 2004  
Addendum to Amendment

CONNECTOR CLIP OF  
JP, A, 11-6591

FIG. C

